



Wayne

Denison Mines (USA) Corp.
1050 17th Street, Suite 950
Denver, CO 80265
USA

Tel : 303 628-7798
Fax : 303 389-4125

www.denisonmines.com

December 27, 2010

Paul Baker
State of Utah, Department of Natural Resources
Department of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

RECEIVED

DEC 29 2010

DIV. OF OIL, GAS & MINING

Paul Baker:

Re: Submission of Annual Reports for Utah Permits, Denison Mines (USA) Corp., Tony M (M/017/0049), La Sal/Snowball (M/370/026), Redd Block Four (M/037/0046), Rim-Columbus (M/370/006), Pandora (M/037/012).

Denison Mines (USA) Corp. is providing annual reports for the above referenced mines. Maps these mines have not changed from the maps currently on file with you.

Please contact me (303) 389-4136 if you have any questions.

Respectfully,

A handwritten signature in cursive script that reads "Christy Woodward".

Christy Woodward, P.E.
Environmental Coordinator
Denison Mines Corp.

CC: Denison File
Terry Wetz, Denison Mines (USA) Corp.
Philip Buck, Denison Mines (USA) Corp.

Enclosure.

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
 1594 West North Temple - Suite 1210
 Box 145801
 Salt Lake City, Utah 84114-5801
 Telephone: (801) 538-5291
 Fax: (801) 359-3940

LARGE MINING OPERATIONS 2009 PROGRESS REPORT
January 1, 2009 to December 31, 2009

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: M/01710049
2. Mine Name: Tony M mine
3. Name of Operator/Permittee: Devision mines (USA) Corp.

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf.

4. Mine Location: Sections 8, 9, 16, 17, and 21. T 35S, R 11E
5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):

Gross Ore Mined 0 Tons, or 0 yd³
 Waste Material Moved 0 Tons, or 0 yd³
 New Disturbance 0 Acres during 2009
 Area Reclaimed 0 Acres during 2009
 Total Disturbed Area 47.62 Acres*

*Total mine disturbance from the beginning of mining operations through the end of 2009.

Was the ore shipped off site? If not, where is the ore located? N/A

Where is the waste located? Existing waste is located in the designated waste rock stock pile area.

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE (https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf) to apply for full or partial bond/site release).

No reclamation work was completed in 2010.

7. For large mines, include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105). Current maps are on file with the Division.

I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): Philip Buck
 Title of Operator: Vice President - Mining
 Signature of Operator: Philip Buck
 Date: 12/17/10